## Narbrook Park East Branch Indian Creek

# **Existing Conditions / Site Analysis**

Julie A. Snell ISA, AOLCP Principal, TEND landscape inc.

> jsnell@tendlandscape.com www.tendlandscape.com




### Narbrook Park East Branch Indian Creek




beautiful place

amazing resource


great potential




Observed existing conditions with a focus on health, function and aesthetics of the landscape.







## Piped and Channelized creek



Constricted flow increases velocity




# Erosion at the end of the channel




Eroded bank at end of channel wall



Scoured and eroded banks Invasive species flourish



# Invasive plants



## Street runoff piped directly into stream

### Creek re-enters pipe and channel on south end








Contributes to manicured park-like feel Extensive mown area



Condition of lawn varies



# Worn and compacted from foot traffic





Arboretum-quality landscape

- Biodiversity
- Visual interest
- Erosion control



Assess trees for health, safety, and landscape contribution




# View from north entrance blocked by declining hemlock

# Future Needs: LONGTERM VEGETATION AND WATER RESOURCES MANAGEMENT STRATEGY





#### NARBROOK PARK



TEND

landscape inc.





Possible location for "1-4-1"



### Daffodil Meadow






#### Possible location for Daffodil Meadow




### Demonstration Rain Garden



### Possible location for a demonstration raingarden



#### NARBROOK PARK



TEND

landscape inc.

Narbrook Park East Branch Indian Creek Existing Conditions

Julie A. Snell ISA, AOLCP Principal, TEND landscape inc.

> jsnell@tendlandscape.com www.tendlandscape.com

